

Line Log

Line Name: BOBS08-04-002
 Start time: 05/05/2008 00:08:46

Client: Bass Strait (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1001	05/05/2008 00:08:45	: Start of line BOBS08-04-002 shot 1001
	05/05/2008 00:08:47	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	05/05/2008 00:08:47	: SOL String pressures 1:2062.0 PSI 2:2018.0 PSI 3:1982.0 PSI
	05/05/2008 00:08:47	: First good shot 1001. Line 'BOBS08-04-002' time 5-5-2008 0:8:46.746813
	05/05/2008 00:08:47	: Atmospheric pressure transducer - 1026 mB
1096	05/05/2008 00:25:25	: Phone String_3:Cluster_1:Phone 1 suspect autofire 1.3s into shot
1100	05/05/2008 00:26:04	: Volume source 1 changed from 3040 to 2790 cu in (ideal volume 3040) 91.8%
	05/05/2008 00:26:05	: String_3 Cluster_1 Gun 1 (250 cu in) failed to detect fire.
	05/05/2008 00:26:05	: String_3 Cluster_1 Gun 1 Solenoid volts and current look OK.
1101	05/05/2008 00:26:15	: String_3 Cluster_1 Gun 1 (250 cu in) failed to detect fire.
	05/05/2008 00:26:15	: String_3 Cluster_1 Gun 1 Solenoid volts and current look OK.
	05/05/2008 00:26:21	: Operator command, GUN String_3 Cluster_1 Gun 2 Enable
	05/05/2008 00:26:22	: Operator command, GUN String_3 Cluster_1 Gun 1 Disable
1102	05/05/2008 00:26:25	: Volume source 1 changed from 2790 to 3040 cu in (ideal volume 3040) 100.0%
	05/05/2008 00:26:25	: String_3 Cluster_1 Gun 2 (250 cu in) fired 2.3 mS late.
	05/05/2008 00:26:25	: Spread error 3.1mS (limit 3.0mS) earliest String_3 Cluster_4 Gun 7 (error -0.8mS) latest String_3 Cluster_1 Gun 2 (error 2.3mS)
1103	05/05/2008 00:26:36	: String_3 Cluster_1 Gun 2 (250 cu in) fired 2.4 mS early.
1104	05/05/2008 00:26:46	: Pressure Errors: String_3 PT 1 1798.0PSI
	05/05/2008 00:26:46	: Sensor amplitude change error String_1: Cluster_1-Gun 2
1105	05/05/2008 00:26:56	: Pressure Errors: String_3 PT 1 1783.0PSI
1106	05/05/2008 00:27:06	: Pressure Errors: String_3 PT 1 1769.0PSI
1107	05/05/2008 00:27:17	: Pressure Errors: String_3 PT 1 1765.0PSI
1108	05/05/2008 00:27:27	: Pressure Errors: String_3 PT 1 1755.0PSI
	05/05/2008 00:27:28	: Operator command, GUNs String_3 Disable
1109	05/05/2008 00:27:37	: Volume source 1 changed from 3040 to 2130 cu in (ideal volume 3040) 70.1%
	05/05/2008 00:27:42	: Operator command, GUNs String_3 Enable
	05/05/2008 00:27:45	: Operator command, GUN String_3 Cluster_1 Gun 1 Disable
1110	05/05/2008 00:27:48	: Volume source 1 changed from 2130 to 3140 cu in (ideal volume 3040) 103.3%
	05/05/2008 00:27:48	: Pressure Errors: String_3 PT 1 1769.0PSI
	05/05/2008 00:27:48	: String_3 Cluster_3 Gun 6 (100 cu in) fired 3.0 mS late.
	05/05/2008 00:27:48	: Spread error 3.2mS (limit 3.0mS) earliest String_3 Cluster_2 Gun 3 (error -0.2mS) latest String_3 Cluster_3 Gun 6 (error 3.0mS)
1111	05/05/2008 00:27:58	: LOST SHOT - TCU did not detect T0 - Failed to see fire signal before timeout (predict settings wrong ?)
	05/05/2008 00:28:04	: END OF LINE shot 1111 time 1-1-1970 0:0:0.0
	05/05/2008 00:28:04	: Atmospheric pressure transducer - 1028 mB
	05/05/2008 00:28:04	: EOL Volume source 1 3140 cu in.
	05/05/2008 00:28:04	: EOL String pressures 1:1942.0 PSI 2:1902.0 PSI 3:1743.0 PSI
		Total shotpoints on line = 111. Shotpoints with errors of any type 11 (9.9%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 6 (5.4%)
		Shotpoints with misfires 2 (1.8%)

Line Log: BOBS08-04-002 (continued)

Shotpoint	Log Time	Message
		Shotpoints with bad timing 4 (3.6%)
		Shotpoints with gun pressure errors 7 (6.3%)