

Line Log

Line Name: BOBS08-05-011
Start time: 27/05/2008 18:43:56

Client: Bass Strait (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1001	27/05/2008 18:43:54	: Start of line BOBS08-05-011 shot 1001
	27/05/2008 18:43:56	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	27/05/2008 18:43:56	: SOL String pressures 1:2057.0 PSI 2:2028.0 PSI 3:1978.0 PSI
	27/05/2008 18:43:57	: First good shot 1001. Line 'BOBS08-05-011' time 5-27-2008 18:43:56.320806
	27/05/2008 18:43:57	: Atmospheric pressure transducer - 1034 mB
1369	27/05/2008 19:44:10	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1941	27/05/2008 21:16:45	: Sensor amplitude change error String_1: Cluster_4-Gun 7
2127	27/05/2008 21:46:35	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5979
	27/05/2008 21:46:35	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5979
	27/05/2008 21:46:35	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	27/05/2008 21:46:35	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 21:46:35	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 21:46:35	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 21:46:35	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 21:46:35	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 21:46:35	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 21:46:35	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 21:46:35	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 21:46:35	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 21:46:36	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/05/2008 21:46:36	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/05/2008 21:46:36	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/05/2008 21:46:36	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/05/2008 21:46:36	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/05/2008 21:46:36	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95979 scans of data in one second !!
	27/05/2008 21:46:36	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/05/2008 21:46:36	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95979 scans of data in one second !!
	27/05/2008 21:46:36	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot

Line Log: BOBS08-05-011 (continued)

Shotpoint	Log Time	Message
	27/05/2008 21:46:36	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: LOST SHOT - Failed to detect T0 from Nodes
	27/05/2008 21:46:36	: Node(s) 1,2 FAILED to report fired status
	27/05/2008 21:46:36	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/05/2008 21:46:36	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	27/05/2008 21:46:36	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
2194	27/05/2008 21:57:18	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6469
	27/05/2008 21:57:18	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6469
	27/05/2008 21:57:18	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:18	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 21:57:19	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	27/05/2008 21:57:19	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 96469 scans of data in one second !!
	27/05/2008 21:57:19	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	27/05/2008 21:57:19	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!

Line Log: BOBS08-05-011 (continued)

Shotpoint	Log Time	Message
	27/05/2008 21:57:19	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/05/2008 21:57:19	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/05/2008 21:57:19	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/05/2008 21:57:19	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96469 scans of data in one second !!
	27/05/2008 21:57:19	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: LOST SHOT - Failed to detect T0 from Nodes
	27/05/2008 21:57:19	: Node(s) 1,2 FAILED to report fired status
	27/05/2008 21:57:19	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	27/05/2008 21:57:19	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
2441	27/05/2008 22:36:55	: Volume source 1 changed from 3040 to 2890 cu in (ideal volume 3040) 95.1%
	27/05/2008 22:36:56	: String_3 Cluster_4 Gun 7 (150 cu in) failed to detect fire.
	27/05/2008 22:36:56	: String_3 Cluster_4 Gun 7 Solenoid volts and current look OK.
2442	27/05/2008 22:37:05	: String_3 Cluster_4 Gun 7 (150 cu in) failed to detect fire.
	27/05/2008 22:37:05	: String_3 Cluster_4 Gun 7 Solenoid volts and current look OK.
2443	27/05/2008 22:37:15	: String_3 Cluster_4 Gun 7 (150 cu in) failed to detect fire.
	27/05/2008 22:37:15	: String_3 Cluster_4 Gun 7 Solenoid volts and current look OK.
2444	27/05/2008 22:37:24	: String_3 Cluster_4 Gun 7 (150 cu in) failed to detect fire.
	27/05/2008 22:37:24	: String_3 Cluster_4 Gun 7 Solenoid volts and current look OK.
2445	27/05/2008 22:37:34	: String_3 Cluster_4 Gun 7 (150 cu in) failed to detect fire.
	27/05/2008 22:37:34	: String_3 Cluster_4 Gun 7 Solenoid volts and current look OK.
	27/05/2008 22:37:38	: Operator command, GUN String_3 Cluster_4 Gun 7 Disable
2454	27/05/2008 22:39:01	: Operator command, GUN String_1 Cluster_2 Gun 4 Enable
2455	27/05/2008 22:39:09	: Volume source 1 changed from 2890 to 3040 cu in (ideal volume 3040) 100.0%
2804	27/05/2008 23:35:06	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6509
	27/05/2008 23:35:06	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6509
	27/05/2008 23:35:07	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 23:35:07	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 23:35:07	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.70s into shot

Line Log: BOBS08-05-011 (continued)

Shotpoint	Log Time	Message
	27/05/2008 23:35:07	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 23:35:07	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 23:35:07	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 23:35:07	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 23:35:07	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 23:35:07	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.70s into shot
	27/05/2008 23:35:07	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/05/2008 23:35:07	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96509 scans of data in one second !!
	27/05/2008 23:35:07	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:35:07	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:35:07	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:35:07	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:35:07	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:35:07	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:35:07	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:35:07	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:35:07	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:35:07	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/05/2008 23:35:07	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/05/2008 23:35:07	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/05/2008 23:35:07	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/05/2008 23:35:07	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/05/2008 23:35:07	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96509 scans of data in one second !!
	27/05/2008 23:35:07	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: LOST SHOT - Failed to detect T0 from Nodes
	27/05/2008 23:35:07	: Node(s) 1,2 FAILED to report fired status
	27/05/2008 23:35:07	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	27/05/2008 23:35:07	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
2934	27/05/2008 23:56:01	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.76s into shot
	27/05/2008 23:56:01	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.76s into shot

Line Log: BOBS08-05-011 (continued)

Shotpoint	Log Time	Message
	27/05/2008 23:56:01	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.76s into shot
	27/05/2008 23:56:01	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.75s into shot
	27/05/2008 23:56:01	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.75s into shot
	27/05/2008 23:56:01	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.76s into shot
	27/05/2008 23:56:01	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/05/2008 23:56:01	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97039 scans of data in one second !!
	27/05/2008 23:56:01	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.75s into shot
	27/05/2008 23:56:01	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.76s into shot
	27/05/2008 23:56:01	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.76s into shot
	27/05/2008 23:56:01	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	27/05/2008 23:56:01	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/05/2008 23:56:01	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/05/2008 23:56:01	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/05/2008 23:56:01	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/05/2008 23:56:01	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/05/2008 23:56:01	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97039 scans of data in one second !!
	27/05/2008 23:56:01	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: LOST SHOT - Failed to detect T0 from Nodes
	27/05/2008 23:56:01	: Node(s) 1,2 FAILED to report fired status
	27/05/2008 23:56:01	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	27/05/2008 23:56:01	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot

Line Log: BOBS08-05-011 (continued)

Shotpoint	Log Time	Message
	27/05/2008 23:56:27	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7039
	27/05/2008 23:56:27	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7039
3123	28/05/2008 00:27:02	: Timeout on message read from Navigation system
	28/05/2008 00:27:06	: END OF LINE shot 3123 time 5-28-2008 0:26:41.527813
	28/05/2008 00:27:06	: Atmospheric pressure transducer - 1032 mB
	28/05/2008 00:27:06	: EOL Volume source 1 3040 cu in.
	28/05/2008 00:27:06	: EOL String pressures 1:2061.0 PSI 2:2032.0 PSI 3:1959.0 PSI
		Total shotpoints on line = 2123. Shotpoints with errors of any type 9 (0.4%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 9 (0.4%)
		Shotpoints with misfires 5 (0.2%)
		Shotpoints with possible autofires detected 4 (0.2%)