

Line Log

Line Name: BOBS08-06-006
 Start time: 25/05/2008 10:52:07

Client: **Bass Strait (2D Project SEBOA)**
 Contract: **6374**

Shotpoint	Log Time	Message
4545	25/05/2008 10:52:05	: Start of line BOBS08-06-006 shot 4545
	25/05/2008 10:52:07	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	25/05/2008 10:52:07	: SOL String pressures 1:2053.0 PSI 2:2022.0 PSI 3:1976.0 PSI
	25/05/2008 10:52:08	: First good shot 4545. Line 'BOBS08-06-006' time 5-25-2008 10:52:7.404806
	25/05/2008 10:52:08	: Atmospheric pressure transducer - 1037 mB
4347	25/05/2008 11:24:21	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7529
	25/05/2008 11:24:21	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7529
	25/05/2008 11:24:21	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:21	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.80s into shot
	25/05/2008 11:24:22	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 11:24:22	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 11:24:22	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 11:24:22	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 11:24:22	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 11:24:22	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97529 scans of data in one second !!
	25/05/2008 11:24:22	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 11:24:22	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97529 scans of data in one second !!
	25/05/2008 11:24:22	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 11:24:22	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 11:24:22	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 11:24:22	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	25/05/2008 11:24:22	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
4129	25/05/2008 11:59:26	: Sensor amplitude change error String_1: Cluster_5-Gun 8
4081	25/05/2008 12:07:06	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5959
	25/05/2008 12:07:06	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5959
	25/05/2008 12:07:07	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 12:07:07	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 12:07:07	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 12:07:07	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 12:07:07	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 12:07:07	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95959 scans of data in one second !!
	25/05/2008 12:07:07	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 12:07:07	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 12:07:07	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 12:07:07	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95959 scans of data in one second !!
	25/05/2008 12:07:08	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 12:07:08	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 12:07:08	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	25/05/2008 12:07:08	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
3805	25/05/2008 12:50:54	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3661	25/05/2008 13:13:35	: Sensor amplitude change error String_1: Cluster_4-Gun 7
3649	25/05/2008 13:15:26	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3189
	25/05/2008 13:15:26	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3189
	25/05/2008 13:15:26	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 13:15:26	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 13:15:26	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 13:15:26	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 13:15:26	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 13:15:26	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 93189 scans of data in one second !!
	25/05/2008 13:15:26	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.37s into shot
	25/05/2008 13:15:26	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 13:15:26	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 93189 scans of data in one second !!
	25/05/2008 13:15:27	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 13:15:27	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 13:15:27	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	25/05/2008 13:15:27	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.4s into shot
3484	25/05/2008 13:42:22	: Gun Depth Errors: String_2 Cluster_3 7.1M
3401	25/05/2008 13:55:42	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3256	25/05/2008 14:19:00	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 14:19:00	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 14:19:00	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 14:19:00	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 14:19:00	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 14:19:00	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 14:19:00	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 14:19:00	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 14:19:00	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 14:19:01	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 14:19:01	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 14:19:01	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 14:19:01	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95979 scans of data in one second !!
	25/05/2008 14:19:01	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 14:19:01	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 14:19:01	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 14:19:01	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 14:19:01	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	25/05/2008 14:19:01	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	25/05/2008 14:19:01	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	25/05/2008 14:19:25	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5979
	25/05/2008 14:19:25	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5979
	25/05/2008 14:19:25	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 14:19:25	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95979 scans of data in one second !!
3095	25/05/2008 14:44:42	: Gun Depth Errors: String_2 Cluster_3 7.1M
3047	25/05/2008 14:52:24	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2777	25/05/2008 15:35:29	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6009

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 15:35:29	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6009
	25/05/2008 15:35:29	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 15:35:29	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96009 scans of data in one second !!
	25/05/2008 15:35:29	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 15:35:29	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 15:35:29	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 15:35:29	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 15:35:29	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 15:35:29	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 15:35:29	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 15:35:29	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.65s into shot
	25/05/2008 15:35:29	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:29	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 15:35:30	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 15:35:30	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 15:35:30	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 15:35:30	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96009 scans of data in one second !!
	25/05/2008 15:35:30	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 15:35:30	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 15:35:30	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 15:35:30	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 15:35:30	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 15:35:30	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	25/05/2008 15:35:30	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
2453	25/05/2008 16:27:35	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7609
	25/05/2008 16:27:35	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7609
	25/05/2008 16:27:35	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	25/05/2008 16:27:35	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 97609 scans of data in one second !!
	25/05/2008 16:27:35	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	25/05/2008 16:27:35	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 16:27:35	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	25/05/2008 16:27:35	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 16:27:35	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.81s into shot
	25/05/2008 16:27:35	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.81s into shot
	25/05/2008 16:27:35	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.81s into shot
	25/05/2008 16:27:35	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.81s into shot
	25/05/2008 16:27:35	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.81s into shot
	25/05/2008 16:27:35	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.81s into shot
	25/05/2008 16:27:35	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.81s into shot
	25/05/2008 16:27:35	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.81s into shot
	25/05/2008 16:27:35	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	25/05/2008 16:27:35	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 97609 scans of data in one second !!
	25/05/2008 16:27:35	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:35	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:35	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:35	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:35	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:35	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:35	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:35	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:35	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:35	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 16:27:36	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 16:27:36	: Node(s) 1,2 FAILED to report fired status

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 16:27:36	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	25/05/2008 16:27:36	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.8s into shot
2287	25/05/2008 16:54:23	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7799
	25/05/2008 16:54:23	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7799
	25/05/2008 16:54:23	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:23	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.83s into shot
	25/05/2008 16:54:24	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 16:54:24	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97799 scans of data in one second !!
	25/05/2008 16:54:24	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 16:54:24	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 16:54:24	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 16:54:24	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 16:54:24	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 16:54:24	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97799 scans of data in one second !!
	25/05/2008 16:54:24	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.8s into shot

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 16:54:24	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 16:54:24	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 16:54:24	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	25/05/2008 16:54:24	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.8s into shot
1708	25/05/2008 18:25:06	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3979
	25/05/2008 18:25:06	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3979
	25/05/2008 18:25:06	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	25/05/2008 18:25:06	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 93979 scans of data in one second !!
	25/05/2008 18:25:06	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	25/05/2008 18:25:06	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 18:25:06	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.45s into shot
	25/05/2008 18:25:06	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	25/05/2008 18:25:06	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 18:25:06	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	25/05/2008 18:25:06	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 93979 scans of data in one second !!
	25/05/2008 18:25:06	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 18:25:06	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 18:25:06	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 18:25:06	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 18:25:06	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 18:25:06	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 18:25:06	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 18:25:06	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 18:25:06	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 18:25:07	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 18:25:07	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 18:25:07	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	25/05/2008 18:25:07	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	25/05/2008 18:25:07	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.4s into shot
1562	25/05/2008 18:48:05	: Sensor amplitude change error String_1: Cluster_4-Gun 7
1529	25/05/2008 18:53:15	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4449
	25/05/2008 18:53:15	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4449
	25/05/2008 18:53:15	Node 1 ad - DemuxPCI_Thread: 9 further scan sequence errors in last second
	25/05/2008 18:53:15	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 94450 scans of data in one second !!
	25/05/2008 18:53:15	Node 1 ad - DataPCI_Thread: 10 further scan sequence errors in last second
	25/05/2008 18:53:15	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 18:53:15	Node 2 ad - DataPCI_Thread: 10 further scan sequence errors in last second
	25/05/2008 18:53:15	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 18:53:15	Node 2 ad - DemuxPCI_Thread: 9 further scan sequence errors in last second
	25/05/2008 18:53:15	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 94450 scans of data in one second !!
	25/05/2008 18:53:16	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 18:53:16	: Node(s) 1,2 FAILED to report fired status
1474	25/05/2008 19:01:54	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5259

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 19:01:54	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5259
	25/05/2008 19:01:54	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 19:01:54	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95259 scans of data in one second !!
	25/05/2008 19:01:54	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 19:01:54	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 19:01:54	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 19:01:54	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 19:01:54	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 19:01:54	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95259 scans of data in one second !!
	25/05/2008 19:01:54	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:54	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.58s into shot
	25/05/2008 19:01:55	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 19:01:55	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 19:01:55	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 19:01:55	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	25/05/2008 19:01:55	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
1378	25/05/2008 19:17:00	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.52s into shot
	25/05/2008 19:17:00	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.52s into shot
	25/05/2008 19:17:00	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.52s into shot
	25/05/2008 19:17:00	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.52s into shot
	25/05/2008 19:17:00	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.52s into shot
	25/05/2008 19:17:00	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.52s into shot
	25/05/2008 19:17:00	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.52s into shot
	25/05/2008 19:17:00	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.52s into shot
	25/05/2008 19:17:00	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:00	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	25/05/2008 19:17:01	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 19:17:01	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94729 scans of data in one second !!
	25/05/2008 19:17:01	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 19:17:01	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 19:17:01	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	25/05/2008 19:17:01	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 19:17:01	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	25/05/2008 19:17:25	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4729
	25/05/2008 19:17:25	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4729
	25/05/2008 19:17:25	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 19:17:25	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 19:17:25	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 19:17:25	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 94729 scans of data in one second !!
	25/05/2008 19:17:25	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 19:17:25	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
1352	25/05/2008 19:21:07	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1133	25/05/2008 19:55:43	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6269
	25/05/2008 19:55:43	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6269
	25/05/2008 19:55:44	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.68s into shot
	25/05/2008 19:55:44	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 19:55:44	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96269 scans of data in one second !!
	25/05/2008 19:55:44	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 19:55:44	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 19:55:44	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 19:55:44	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96269 scans of data in one second !!
	25/05/2008 19:55:44	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 19:55:44	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!

Line Log: BOBS08-06-006 (continued)

Shotpoint	Log Time	Message
	25/05/2008 19:55:44	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	25/05/2008 19:55:44	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	25/05/2008 19:55:44	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	25/05/2008 19:55:44	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	25/05/2008 19:55:44	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	25/05/2008 19:55:44	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 19:55:44	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 19:55:44	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	25/05/2008 19:55:44	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	25/05/2008 19:55:44	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	25/05/2008 19:55:45	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	25/05/2008 19:55:45	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	25/05/2008 19:55:45	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	25/05/2008 19:55:45	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	25/05/2008 19:55:45	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	25/05/2008 19:55:45	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	25/05/2008 19:55:45	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	25/05/2008 19:55:45	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	25/05/2008 19:55:45	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
1077	25/05/2008 20:04:40	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.29s into shot
1063	25/05/2008 20:06:54	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1053	25/05/2008 20:08:30	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.13s into shot
881	25/05/2008 20:36:17	: Timeout on message read from Navigation system
	25/05/2008 20:36:21	: END OF LINE shot 881 time 5-25-2008 20:35:56.649813
	25/05/2008 20:36:21	: Atmospheric pressure transducer - 1030 mB
	25/05/2008 20:36:21	: EOL Volume source 1 3040 cu in.
	25/05/2008 20:36:21	: EOL String pressures 1:2057.0 PSI 2:2028.0 PSI 3:1980.0 PSI
		Total shotpoints on line = 3665. Shotpoints with errors of any type 15 (0.4%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 13 (0.4%)
		Shotpoints with possible autofires detected 13 (0.4%)
		Shotpoints with gun depth errors 2 (0.1%)