

## Line Log

Line Name: BOBS08-08-018  
 Start time: 30/05/2008 17:56:50

Client: Bass Strait (2D Project SEBOA)  
 Contract: 6374

Shotpoint	Log Time	Message
4906	30/05/2008 17:56:49	: Start of line BOBS08-08-018 shot 4906
	30/05/2008 17:56:51	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	30/05/2008 17:56:51	: SOL String pressures 1:2076.0 PSI 2:2046.0 PSI 3:2000.0 PSI
	30/05/2008 17:56:52	: First good shot 4906. Line 'BOBS08-08-018' time 5-30-2008 17:56:50.943800
	30/05/2008 17:56:52	: Atmospheric pressure transducer - 1036 mB
4692	30/05/2008 18:30:31	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4209
	30/05/2008 18:30:31	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4209
	30/05/2008 18:30:31	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:31	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:31	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:31	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:31	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:31	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:31	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:31	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	30/05/2008 18:30:32	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 18:30:32	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94209 scans of data in one second !!
	30/05/2008 18:30:32	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 18:30:32	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 94209 scans of data in one second !!
	30/05/2008 18:30:32	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 18:30:32	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 18:30:32	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 18:30:32	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 18:30:32	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot

## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	30/05/2008 18:30:32	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 18:30:32	: Node(s) 1,2 FAILED to report fired status
	30/05/2008 18:30:32	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/05/2008 18:30:32	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
4566	30/05/2008 18:50:11	: Sensor amplitude change error String_1: Cluster_4-Gun 7
4481	30/05/2008 19:03:31	: Gun Depth Errors: String_1 Cluster_1 4.8M
4298	30/05/2008 19:31:53	tcucom - main: Lost sync with TCU - didn't see CR when expected - %GD096 looking for 102 got 102 plus %'
4029	30/05/2008 20:14:00	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:00	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.68s into shot
	30/05/2008 20:14:01	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 20:14:01	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96289 scans of data in one second !!
	30/05/2008 20:14:01	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: LOST SHOT - Failed to detect T0 from Nodes

## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	30/05/2008 20:14:01	: Node(s) 1,2 FAILED to report fired status
	30/05/2008 20:14:01	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	30/05/2008 20:14:01	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	30/05/2008 20:14:01	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	30/05/2008 20:14:30	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6289
	30/05/2008 20:14:30	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6289
	30/05/2008 20:14:30	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	30/05/2008 20:14:30	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 20:14:30	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	30/05/2008 20:14:30	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 20:14:30	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	30/05/2008 20:14:30	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 96289 scans of data in one second !!
3590	30/05/2008 21:22:59	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3089	30/05/2008 22:43:36	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9289
	30/05/2008 22:43:36	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9289
	30/05/2008 22:43:36	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	30/05/2008 22:43:36	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 99289 scans of data in one second !!
	30/05/2008 22:43:36	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.98s into shot
	30/05/2008 22:43:36	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.98s into shot
	30/05/2008 22:43:36	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.98s into shot
	30/05/2008 22:43:36	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.98s into shot
	30/05/2008 22:43:36	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.98s into shot
	30/05/2008 22:43:36	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.98s into shot
	30/05/2008 22:43:36	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.98s into shot
	30/05/2008 22:43:36	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.98s into shot
	30/05/2008 22:43:36	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot

## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	30/05/2008 22:43:36	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/05/2008 22:43:36	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 22:43:36	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 22:43:36	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 22:43:36	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 22:43:36	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 22:43:36	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99289 scans of data in one second !!
	30/05/2008 22:43:37	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 22:43:37	: Node(s) 1,2 FAILED to report fired status
	30/05/2008 22:43:37	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	30/05/2008 22:43:37	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
2995	30/05/2008 22:59:06	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6899
	30/05/2008 22:59:06	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6899
	30/05/2008 22:59:06	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 22:59:06	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96900 scans of data in one second !!
	30/05/2008 22:59:07	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 22:59:07	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96900 scans of data in one second !!
	30/05/2008 22:59:07	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second

## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	30/05/2008 22:59:07	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 22:59:07	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	30/05/2008 22:59:07	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 22:59:07	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 22:59:07	: Node(s) 1,2 FAILED to report fired status
2923	30/05/2008 23:10:57	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2900	30/05/2008 23:14:42	: Sensor amplitude change error String_1: Cluster_4-Gun 7
2874	30/05/2008 23:19:04	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2865	30/05/2008 23:20:33	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.27s into shot
2847	30/05/2008 23:23:30	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9119
	30/05/2008 23:23:30	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9119
	30/05/2008 23:23:30	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 23:23:30	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99120 scans of data in one second !!
	30/05/2008 23:23:31	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 23:23:31	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99120 scans of data in one second !!
	30/05/2008 23:23:31	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	30/05/2008 23:23:31	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 23:23:31	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	30/05/2008 23:23:31	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 23:23:31	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 23:23:31	: Node(s) 1,2 FAILED to report fired status
2744	30/05/2008 23:40:39	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.48s into shot
2704	30/05/2008 23:47:19	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2159
	30/05/2008 23:47:19	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2159
	30/05/2008 23:47:19	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:19	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:19	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:19	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:19	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:19	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:19	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:19	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.27s into shot

## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	30/05/2008 23:47:20	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 23:47:20	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 102159 scans of data in one second !!
	30/05/2008 23:47:20	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.27s into shot
	30/05/2008 23:47:20	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 23:47:20	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 102159 scans of data in one second !!
	30/05/2008 23:47:20	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 23:47:20	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 23:47:20	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 23:47:20	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 23:47:20	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 23:47:20	: Node(s) 1,2 FAILED to report fired status
	30/05/2008 23:47:20	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.3s into shot

## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	30/05/2008 23:47:20	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	30/05/2008 23:47:20	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.3s into shot
2457	31/05/2008 00:28:34	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2376	31/05/2008 00:42:10	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.96s into shot
1926	31/05/2008 01:58:45	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.1659
	31/05/2008 01:58:45	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.1659
	31/05/2008 01:58:45	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:45	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.22s into shot
	31/05/2008 01:58:46	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second

## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	31/05/2008 01:58:46	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 101659 scans of data in one second !!
	31/05/2008 01:58:46	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	31/05/2008 01:58:46	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 101659 scans of data in one second !!
	31/05/2008 01:58:46	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	31/05/2008 01:58:46	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	31/05/2008 01:58:46	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	31/05/2008 01:58:46	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	31/05/2008 01:58:46	: Phone String_2:Cluster.1:Phone 1 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: LOST SHOT - Failed to detect T0 from Nodes
	31/05/2008 01:58:46	: Node(s) 1,2 FAILED to report fired status
	31/05/2008 01:58:46	: Phone String_1:Cluster.1:Phone 1 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_2:Cluster.2:Phone 2 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_1:Cluster.2:Phone 2 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_2:Cluster.3:Phone 3 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_2:Cluster.4:Phone 4 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_1:Cluster.3:Phone 3 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_2:Cluster.5:Phone 5 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_1:Cluster.4:Phone 4 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_2:Cluster.6:Phone 6 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_1:Cluster.5:Phone 5 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_3:Cluster.1:Phone 1 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_3:Cluster.2:Phone 2 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_3:Cluster.3:Phone 3 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_3:Cluster.4:Phone 4 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_3:Cluster.5:Phone 5 suspect autofire 10.2s into shot
	31/05/2008 01:58:46	: Phone String_3:Cluster.6:Phone 6 suspect autofire 10.2s into shot
1714	31/05/2008 02:34:54	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2109
	31/05/2008 02:34:54	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2109
	31/05/2008 02:34:54	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	31/05/2008 02:34:54	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 102109 scans of data in one second !!
	31/05/2008 02:34:55	: Gun String_1:Cluster.1:Gun 1 (250 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_1:Cluster.1:Gun 2 (250 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_1:Cluster.2:Gun 3 (150 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_1:Cluster.3:Gun 5 (100 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_1:Cluster.4:Gun 7 (150 cu in) suspect autofire (sensor) 10.26s into shot



## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	31/05/2008 02:34:55	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.26s into shot
	31/05/2008 02:34:55	Node 2 ad - DemuxPCLThread: 8 further scan sequence errors in last second
	31/05/2008 02:34:55	Node 2 ad - DemuxPCLThread: LOST or GAINED 102109 scans of data in one second !!
	31/05/2008 02:34:55	Node 1 ad - DataPCLThread: 9 further scan sequence errors in last second
	31/05/2008 02:34:55	Node 1 ad - DataPCLThread: LOST (but substituted) 1 scans in 1 second !!!
	31/05/2008 02:34:55	Node 2 ad - DataPCLThread: 9 further scan sequence errors in last second
	31/05/2008 02:34:55	Node 2 ad - DataPCLThread: LOST (but substituted) 1 scans in 1 second !!!
	31/05/2008 02:34:55	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: LOST SHOT - Failed to detect T0 from Nodes
	31/05/2008 02:34:55	: Node(s) 1,2 FAILED to report fired status
	31/05/2008 02:34:55	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.3s into shot

## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	31/05/2008 02:34:55	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	31/05/2008 02:34:55	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.3s into shot
1540	31/05/2008 03:04:23	tcucom - main: Lost sync with TCU - didn't see CR when expected - %vR027 looking for 33 got 33 plus '@'
1498	31/05/2008 03:11:26	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1145	31/05/2008 04:09:57	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8769
	31/05/2008 04:09:57	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8769
	31/05/2008 04:09:58	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	31/05/2008 04:09:58	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 98769 scans of data in one second !!
	31/05/2008 04:09:58	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	31/05/2008 04:09:58	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 98769 scans of data in one second !!
	31/05/2008 04:09:58	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.93s into shot
	31/05/2008 04:09:58	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	31/05/2008 04:09:58	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	31/05/2008 04:09:58	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	31/05/2008 04:09:58	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	31/05/2008 04:09:58	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	31/05/2008 04:09:58	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	31/05/2008 04:09:58	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	31/05/2008 04:09:58	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	31/05/2008 04:09:58	: LOST SHOT - Failed to detect T0 from Nodes

## Line Log: BOBS08-08-018 (continued)

Shotpoint	Log Time	Message
	31/05/2008 04:09:58	: Node(s) 1,2 FAILED to report fired status
	31/05/2008 04:09:58	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	31/05/2008 04:09:58	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	31/05/2008 04:09:58	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	31/05/2008 04:09:59	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.9s into shot
1032	31/05/2008 04:28:35	: Sensor amplitude change error String_1: Cluster_4-Gun 7
881	31/05/2008 04:53:45	: Timeout on message read from Navigation system
	31/05/2008 04:53:49	: END OF LINE shot 881 time 5-31-2008 4:53:23.946800
	31/05/2008 04:53:49	: Atmospheric pressure transducer - 1030 mB
	31/05/2008 04:53:49	: EOL Volume source 1 3040 cu in.
	31/05/2008 04:53:49	: EOL String pressures 1:2053.0 PSI 2:2025.0 PSI 3:1982.0 PSI
		Total shotpoints on line = 4026. Shotpoints with errors of any type 10 (0.2%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 0 (0.0%)
		Shotpoints with possible autofires detected 9 (0.2%)
		Shotpoints with gun depth errors 1 (0.0%)