

## Line Log

Line Name: BOBS08-11-017  
 Start time: 30/05/2008 06:12:00

Client: **Bass Strait (2D Project SEBOA)**  
 Contract: **6374**

Shotpoint	Log Time	Message
1001	30/05/2008 06:11:58	: Start of line BOBS08-11-017 shot 1001
	30/05/2008 06:12:01	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	30/05/2008 06:12:01	: SOL String pressures 1:2051.0 PSI 2:2024.0 PSI 3:1977.0 PSI
	30/05/2008 06:12:01	: First good shot 1001. Line 'BOBS08-11-017' time 5-30-2008 6:12:0.765806
	30/05/2008 06:12:01	: Atmospheric pressure transducer - 1035 mB
1322	30/05/2008 07:04:16	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4509
	30/05/2008 07:04:16	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4509
	30/05/2008 07:04:16	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 07:04:16	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 07:04:16	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.50s into shot
	30/05/2008 07:04:16	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 07:04:16	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 07:04:17	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 07:04:17	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94509 scans of data in one second !!
	30/05/2008 07:04:17	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 07:04:17	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 94509 scans of data in one second !!
	30/05/2008 07:04:17	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Node(s) 1,2 FAILED to report fired status

## Line Log: BOBS08-11-017 (continued)

Shotpoint	Log Time	Message
	30/05/2008 07:04:17	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 07:04:17	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/05/2008 07:04:17	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
1599	30/05/2008 07:48:34	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5999
	30/05/2008 07:48:34	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5999
	30/05/2008 07:48:34	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 07:48:34	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 07:48:34	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:34	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 07:48:34	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 07:48:35	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 07:48:35	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95999 scans of data in one second !!
	30/05/2008 07:48:35	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:35	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:35	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:35	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:35	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:35	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:35	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.65s into shot
	30/05/2008 07:48:35	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 07:48:35	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95999 scans of data in one second !!

## Line Log: BOBS08-11-017 (continued)

Shotpoint	Log Time	Message
	30/05/2008 07:48:35	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 07:48:35	: Node(s) 1,2 FAILED to report fired status
	30/05/2008 07:48:35	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	30/05/2008 07:48:35	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
1867	30/05/2008 08:31:39	tcucom - process_tcu_message: Common clock was 1010 milli seconds fast
1895	30/05/2008 08:36:08	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6999
	30/05/2008 08:36:08	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6999
	30/05/2008 08:36:08	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 08:36:08	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96999 scans of data in one second !!
	30/05/2008 08:36:08	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.75s into shot
	30/05/2008 08:36:08	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.75s into shot

## Line Log: BOBS08-11-017 (continued)

Shotpoint	Log Time	Message
	30/05/2008 08:36:08	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 08:36:08	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 08:36:09	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 08:36:09	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 08:36:09	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 08:36:09	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96999 scans of data in one second !!
	30/05/2008 08:36:09	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 08:36:09	: Node(s) 1,2 FAILED to report fired status
	30/05/2008 08:36:09	: Phone String_2:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_2:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_1:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_2:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_1:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_2:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_1:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_2:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_1:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_2:Cluster.6:Phone 6 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_1:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_3:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_3:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_3:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_3:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_3:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	30/05/2008 08:36:09	: Phone String_3:Cluster.6:Phone 6 suspect autofire 9.8s into shot
2634	30/05/2008 10:38:36	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3196	30/05/2008 12:10:06	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5409
	30/05/2008 12:10:06	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5409
	30/05/2008 12:10:06	: Gun String_1:Cluster.1:Gun 1 (250 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_1:Cluster.1:Gun 2 (250 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_1:Cluster.2:Gun 3 (150 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_1:Cluster.3:Gun 5 (100 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_1:Cluster.5:Gun 8 (70 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_1:Cluster.6:Gun 9 (40 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_3:Cluster.6:Gun 9 (40 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_2:Cluster.2:Gun 3 (300 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_2:Cluster.2:Gun 4 (300 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_2:Cluster.3:Gun 5 (100 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_2:Cluster.6:Gun 8 (70 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_3:Cluster.1:Gun 1 (250 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_3:Cluster.2:Gun 3 (150 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_3:Cluster.2:Gun 4 (150 cu in) suspect autofire (sensor) 9.59s into shot

## Line Log: BOBS08-11-017 (continued)

Shotpoint	Log Time	Message
	30/05/2008 12:10:06	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:06	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.59s into shot
	30/05/2008 12:10:07	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 12:10:07	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95409 scans of data in one second !!
	30/05/2008 12:10:07	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 12:10:07	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 12:10:07	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 12:10:07	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 12:10:07	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 12:10:07	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95409 scans of data in one second !!
	30/05/2008 12:10:07	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 12:10:07	: Node(s) 1,2 FAILED to report fired status
	30/05/2008 12:10:07	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	30/05/2008 12:10:07	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
3375	30/05/2008 12:39:11	tcucom - main: Lost sync with TCU - didn't see CR when expected - %GD096 looking for 102 got 102 plus ' '
3380	30/05/2008 12:39:54	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9919
	30/05/2008 12:39:54	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9919
	30/05/2008 12:39:55	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 12:39:55	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99919 scans of data in one second !!
	30/05/2008 12:39:55	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.04s into shot

## Line Log: BOBS08-11-017 (continued)

Shotpoint	Log Time	Message
	30/05/2008 12:39:55	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	30/05/2008 12:39:55	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 12:39:55	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.04s into shot
	30/05/2008 12:39:55	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	30/05/2008 12:39:55	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 12:39:55	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	30/05/2008 12:39:55	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 99919 scans of data in one second !!
	30/05/2008 12:39:55	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 12:39:55	: Node(s) 1,2 FAILED to report fired status
	30/05/2008 12:39:55	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot

## Line Log: BOBS08-11-017 (continued)

Shotpoint	Log Time	Message
	30/05/2008 12:39:55	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	30/05/2008 12:39:55	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
3543	30/05/2008 13:07:46	: Timeout on message read from Navigation system
	30/05/2008 13:07:50	: END OF LINE shot 3543 time 5-30-2008 13:7:25.520806
	30/05/2008 13:07:50	: Atmospheric pressure transducer - 1035 mB
	30/05/2008 13:07:50	: EOL Volume source 1 3040 cu in.
	30/05/2008 13:07:50	: EOL String pressures 1:2055.0 PSI 2:2025.0 PSI 3:1980.0 PSI
		Total shotpoints on line = 2543. Shotpoints with errors of any type 5 (0.2%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 0 (0.0%)
		Shotpoints with possible autofires detected 5 (0.2%)