

## Line Log

Line Name: BOBS08-13-016  
 Start time: 29/05/2008 21:23:49

Client: Bass Strait (2D Project SEBOA)  
 Contract: 6374

Shotpoint	Log Time	Message
3612	29/05/2008 21:23:47	: Start of line BOBS08-13-016 shot 3612
	29/05/2008 21:23:49	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	29/05/2008 21:23:49	: SOL String pressures 1:2036.0 PSI 2:2006.0 PSI 3:1959.0 PSI
	29/05/2008 21:23:50	: First good shot 3612. Line 'BOBS08-13-016' time 5-29-2008 21:23:49.097825
	29/05/2008 21:23:50	: Atmospheric pressure transducer - 1031 mB
3387	29/05/2008 21:59:44	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.19s into shot
2879	29/05/2008 23:22:06	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9079
	29/05/2008 23:22:06	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9079
	29/05/2008 23:22:06	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 23:22:06	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99079 scans of data in one second !!
	29/05/2008 23:22:06	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 23:22:06	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99079 scans of data in one second !!
	29/05/2008 23:22:06	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.96s into shot
	29/05/2008 23:22:06	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 23:22:06	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 23:22:06	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 23:22:06	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 23:22:06	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 23:22:06	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 23:22:06	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 23:22:06	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 23:22:06	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 23:22:06	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 23:22:06	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 23:22:07	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: LOST SHOT - Failed to detect T0 from Nodes
	29/05/2008 23:22:07	: Node(s) 1,2 FAILED to report fired status

## Line Log: BOBS08-13-016 (continued)

Shotpoint	Log Time	Message
	29/05/2008 23:22:07	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	29/05/2008 23:22:07	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
2666	29/05/2008 23:57:17	: Sensor amplitude change error String_1: Cluster_4-Gun 7
2282	30/05/2008 01:01:14	: String_2 Cluster_6 Gun 8 ( 70 cu in) fired 1.8 mS late.
1973	30/05/2008 01:52:13	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0769
	30/05/2008 01:52:13	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0769
	30/05/2008 01:52:13	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	30/05/2008 01:52:13	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 01:52:13	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	30/05/2008 01:52:13	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 01:52:13	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:13	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:13	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:13	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:13	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:13	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:13	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:13	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:13	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:13	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:14	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.13s into shot

## Line Log: BOBS08-13-016 (continued)

Shotpoint	Log Time	Message
	30/05/2008 01:52:14	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:14	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:14	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:14	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:14	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:14	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.13s into shot
	30/05/2008 01:52:14	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 01:52:14	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 100769 scans of data in one second !!
	30/05/2008 01:52:14	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/05/2008 01:52:14	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 100769 scans of data in one second !!
	30/05/2008 01:52:14	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 01:52:14	: Node(s) 1,2 FAILED to report fired status
	30/05/2008 01:52:14	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	30/05/2008 01:52:14	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.1s into shot
1932	30/05/2008 01:59:02	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.17s into shot
1921	30/05/2008 02:00:51	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.22s into shot
1662	30/05/2008 02:43:51	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9069
	30/05/2008 02:43:51	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9069
	30/05/2008 02:43:52	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	30/05/2008 02:43:52	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99070 scans of data in one second !!
	30/05/2008 02:43:52	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second

## Line Log: BOBS08-13-016 (continued)

Shotpoint	Log Time	Message
	30/05/2008 02:43:52	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99070 scans of data in one second !!
	30/05/2008 02:43:52	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	30/05/2008 02:43:52	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 02:43:52	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	30/05/2008 02:43:52	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/05/2008 02:43:52	: LOST SHOT - Failed to detect T0 from Nodes
	30/05/2008 02:43:52	: Node(s) 1,2 FAILED to report fired status
1528	30/05/2008 03:06:04	: Sensor amplitude change error String_1: Cluster_5-Gun 8
881	30/05/2008 04:54:36	: Timeout on message read from Navigation system
	30/05/2008 04:54:40	: END OF LINE shot 881 time 5-30-2008 4:54:15.361819
	30/05/2008 04:54:40	: Atmospheric pressure transducer - 1034 mB
	30/05/2008 04:54:40	: EOL Volume source 1 3040 cu in.
	30/05/2008 04:54:40	: EOL String pressures 1:2053.0 PSI 2:2024.0 PSI 3:1978.0 PSI
		Total shotpoints on line = 2732. Shotpoints with errors of any type 6 (0.2%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 1 (0.0%)
		Shotpoints with bad timing 1 (0.0%)
		Shotpoints with possible autofires detected 5 (0.2%)