

Line Log

Line Name: BOBS08-15-014
 Start time: 29/05/2008 01:35:43

Client: Bass Strait (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
4002	29/05/2008 01:35:41	: Start of line BOBS08-15-014 shot 4002
	29/05/2008 01:35:44	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	29/05/2008 01:35:44	: SOL String pressures 1:2065.0 PSI 2:2036.0 PSI 3:1987.0 PSI
	29/05/2008 01:35:44	: First good shot 4002. Line 'BOBS08-15-014' time 5-29-2008 1:35:43.675813
	29/05/2008 01:35:44	: Atmospheric pressure transducer - 1044 mB
3896	29/05/2008 01:52:57	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.22s into shot
3846	29/05/2008 02:01:02	: Sensor amplitude change error String_1: Cluster_4-Gun 7
3801	29/05/2008 02:08:17	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6289
	29/05/2008 02:08:17	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6289
	29/05/2008 02:08:17	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 02:08:17	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 02:08:17	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 02:08:17	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 02:08:18	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 02:08:18	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96289 scans of data in one second !!
	29/05/2008 02:08:18	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 02:08:18	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96289 scans of data in one second !!
	29/05/2008 02:08:18	: LOST SHOT - Failed to detect T0 from Nodes
	29/05/2008 02:08:18	: Node(s) 1,2 FAILED to report fired status
3252	29/05/2008 03:36:44	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.18s into shot
3151	29/05/2008 03:52:57	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3065	29/05/2008 04:06:42	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.37s into shot
3064	29/05/2008 04:06:58	: Operator command, GUN String_1 Cluster_5 Gun 8 New Threshold
3063	29/05/2008 04:06:59	: Operator command, GUN String_1 Cluster_5 Gun 8 New Threshold
	29/05/2008 04:07:00	: Operator command, GUN String_1 Cluster_5 Gun 8 New Threshold
2917	29/05/2008 04:30:32	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2751	29/05/2008 04:57:11	: Sensor amplitude change error String_1: Cluster_4-Gun 7
2669	29/05/2008 05:10:13	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2596	29/05/2008 05:21:53	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.28s into shot
2583	29/05/2008 05:24:00	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2527	29/05/2008 05:33:00	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.17s into shot
2411	29/05/2008 05:51:43	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2291	29/05/2008 06:11:09	tcucom - main: Lost sync with TCU - didn't see CR when expected - %MA013 looking for 19 got 19 plus '0'
	29/05/2008 06:11:09	tcucom - main: Repeating arm message as not seen response from TCU
2140	29/05/2008 06:35:12	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1990	29/05/2008 06:59:08	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6039

Line Log: BOBS08-15-014 (continued)

Shotpoint	Log Time	Message
	29/05/2008 06:59:08	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6039
	29/05/2008 06:59:08	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 06:59:08	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 06:59:08	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 06:59:08	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96039 scans of data in one second !!
	29/05/2008 06:59:08	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.65s into shot
	29/05/2008 06:59:08	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	29/05/2008 06:59:08	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:08	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.66s into shot
	29/05/2008 06:59:09	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 06:59:09	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96039 scans of data in one second !!
	29/05/2008 06:59:09	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 06:59:09	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 06:59:09	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: LOST SHOT - Failed to detect T0 from Nodes
	29/05/2008 06:59:09	: Node(s) 1,2 FAILED to report fired status
	29/05/2008 06:59:09	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.7s into shot

Line Log: BOBS08-15-014 (continued)

Shotpoint	Log Time	Message
	29/05/2008 06:59:09	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	29/05/2008 06:59:09	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
1953	29/05/2008 07:05:02	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1952	29/05/2008 07:05:10	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4829
	29/05/2008 07:05:10	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4829
	29/05/2008 07:05:11	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 07:05:11	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94829 scans of data in one second !!
	29/05/2008 07:05:11	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 07:05:11	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 07:05:11	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.53s into shot
	29/05/2008 07:05:11	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 07:05:11	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 07:05:11	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 07:05:11	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 07:05:11	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 07:05:11	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 07:05:11	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 07:05:11	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 07:05:11	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	29/05/2008 07:05:11	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 07:05:11	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 94829 scans of data in one second !!
	29/05/2008 07:05:11	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: LOST SHOT - Failed to detect T0 from Nodes
	29/05/2008 07:05:11	: Node(s) 1,2 FAILED to report fired status
	29/05/2008 07:05:11	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot

Line Log: BOBS08-15-014 (continued)

Shotpoint	Log Time	Message
	29/05/2008 07:05:11	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	29/05/2008 07:05:11	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	29/05/2008 07:05:12	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	29/05/2008 07:05:12	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	29/05/2008 07:05:12	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	29/05/2008 07:05:12	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
1906	29/05/2008 07:12:30	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5919
	29/05/2008 07:12:30	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5919
	29/05/2008 07:12:31	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 07:12:31	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95919 scans of data in one second !!
	29/05/2008 07:12:31	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 07:12:31	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 07:12:31	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 07:12:31	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 07:12:31	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 07:12:31	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95919 scans of data in one second !!
	29/05/2008 07:12:32	: LOST SHOT - Failed to detect T0 from Nodes
	29/05/2008 07:12:32	: Node(s) 1,2 FAILED to report fired status
1905	29/05/2008 07:12:40	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.17s into shot
1861	29/05/2008 07:19:42	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5799
	29/05/2008 07:19:42	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5799
	29/05/2008 07:19:42	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.63s into shot

Line Log: BOBS08-15-014 (continued)

Shotpoint	Log Time	Message
	29/05/2008 07:19:42	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:42	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.63s into shot
	29/05/2008 07:19:43	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 07:19:43	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95799 scans of data in one second !!
	29/05/2008 07:19:43	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 07:19:43	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 07:19:43	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 07:19:43	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 07:19:43	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 07:19:43	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95799 scans of data in one second !!
	29/05/2008 07:19:43	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: LOST SHOT - Failed to detect T0 from Nodes
	29/05/2008 07:19:43	: Node(s) 1,2 FAILED to report fired status
	29/05/2008 07:19:43	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	29/05/2008 07:19:43	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
1838	29/05/2008 07:23:22	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.12s into shot
1368	29/05/2008 08:38:04	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6389
	29/05/2008 08:38:04	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6389
	29/05/2008 08:38:05	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 08:38:05	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96389 scans of data in one second !!
	29/05/2008 08:38:05	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 08:38:05	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 08:38:05	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 08:38:05	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!

Line Log: BOBS08-15-014 (continued)

Shotpoint	Log Time	Message
	29/05/2008 08:38:05	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 08:38:05	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96389 scans of data in one second !!
	29/05/2008 08:38:06	: LOST SHOT - Failed to detect T0 from Nodes
	29/05/2008 08:38:06	: Node(s) 1,2 FAILED to report fired status
1138	29/05/2008 09:17:44	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1117	29/05/2008 09:21:24	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4929
	29/05/2008 09:21:24	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4929
	29/05/2008 09:21:24	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 09:21:24	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 104929 scans of data in one second !!
	29/05/2008 09:21:24	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 09:21:24	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 09:21:24	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	29/05/2008 09:21:24	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	29/05/2008 09:21:24	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	29/05/2008 09:21:24	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 104929 scans of data in one second !!
	29/05/2008 09:21:24	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.54s into shot

Line Log: BOBS08-15-014 (continued)

Shotpoint	Log Time	Message
	29/05/2008 09:21:24	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:24	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.54s into shot
	29/05/2008 09:21:25	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: LOST SHOT - Failed to detect T0 from Nodes
	29/05/2008 09:21:25	: Node(s) 1,2 FAILED to report fired status
	29/05/2008 09:21:25	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	29/05/2008 09:21:25	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.5s into shot
1015	29/05/2008 09:38:41	: Sensor amplitude change error String_1: Cluster_5-Gun 8
891	29/05/2008 09:58:13	: Sensor amplitude change error String_1: Cluster_5-Gun 8
881	29/05/2008 10:00:06	: Timeout on message read from Navigation system
	29/05/2008 10:00:10	: END OF LINE shot 881 time 5-29-2008 9:59:45.110813
	29/05/2008 10:00:10	: Atmospheric pressure transducer - 1046 mB
	29/05/2008 10:00:10	: EOL Volume source 1 3040 cu in.
	29/05/2008 10:00:10	: EOL String pressures 1:2049.0 PSI 2:2020.0 PSI 3:1974.0 PSI
		Total shotpoints on line = 3122. Shotpoints with errors of any type 11 (0.4%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 0 (0.0%)
		Shotpoints with possible autofires detected 11 (0.4%)