

Standard:	PXTAS1A			PXTAS2		
	mean	St dev	Acceptable range	mean	St dev	Acceptable range
Cu	480	150	180 to 780	3560	1090	1380 to 5740
Pb	4050	980	2090 to 6010	10380	2010	6360 to 14400
Zn	21780	5650	10480 to 33080	16430	4510	7410 to 25450
Ag	8.6	7.1	0 to 22.8	34	34	0 to 102
As	89	81	0 to 251	8650	3720	1210 to 16090
Ba	1710	370	970 to 2450	3240	790	1660 to 4820
	ppb	ppb	ppb	ppb	ppb	ppb