

| Frontier Resources Ltd | | | | Drill Core Recovery & RQD Log | | | |
|------------------------|------|------|----------|-------------------------------|-----------|--------------|-------|
| Hole_ID | From | To | Interval | Measured | Recovery% | Lengths>10cm | RQD % |
| NC 59 | 0 | 1.5 | 1.5 | 0 | 0.00 | 0 | 0.00 |
| NC 59 | 1.5 | 3 | 1.5 | 0.6 | 40.00 | 0.25 | 16.67 |
| NC 59 | 3 | 4.5 | 1.5 | 0.95 | 63.33 | 0.25 | 16.67 |
| NC 59 | 4.5 | 6 | 1.5 | 1.5 | 100.00 | 0.4 | 26.67 |
| NC 59 | 6 | 7.5 | 1.5 | 1.5 | 100.00 | 0 | 0.00 |
| NC 59 | 7.5 | 9 | 1.5 | 1.5 | 100.00 | 0.1 | 6.67 |
| NC 59 | 9 | 10.5 | 1.5 | 0.75 | 50.00 | 0 | 0.00 |
| NC 59 | 10.5 | 12 | 1.5 | 1.1 | 73.33 | 0 | 0.00 |
| NC 59 | 12 | 13.5 | 1.5 | 1.3 | 86.67 | 0 | 0.00 |
| NC 59 | 13.5 | 15 | 1.5 | 1.15 | 76.67 | 0 | 0.00 |
| NC 59 | 15 | 16.5 | 1.5 | 1.4 | 93.33 | 0.2 | 13.33 |
| NC 59 | 16.5 | 18 | 1.5 | 1.4 | 93.33 | 0 | 0.00 |
| NC 59 | 18 | 19.5 | 1.5 | 1.5 | 100.00 | 0.3 | 20.00 |
| NC 59 | 19.5 | 21 | 1.5 | 1.5 | 100.00 | 0.85 | 56.67 |
| NC 59 | 21 | 22.5 | 1.5 | 1.5 | 100.00 | 0.65 | 43.33 |
| NC 59 | 22.5 | 24 | 1.5 | 1.5 | 100.00 | 0.5 | 33.33 |
| NC 59 | 24 | 25.5 | 1.5 | 1.5 | 100.00 | 0.7 | 46.67 |
| NC 59 | 25.5 | 27 | 1.5 | 1.5 | 100.00 | 1.1 | 73.33 |
| NC 59 | 27 | 28.5 | 1.5 | 1.5 | 100.00 | 1.15 | 76.67 |
| NC 59 | 28.5 | 30 | 1.5 | 1.5 | 100.00 | 1.1 | 73.33 |
| NC 59 | 30 | 31.5 | 1.5 | 1.5 | 100.00 | 1.2 | 80.00 |
| NC 59 | 31.5 | 33 | 1.5 | 1.5 | 100.00 | 1.15 | 76.67 |
| NC 59 | 33 | 34.5 | 1.5 | 1.5 | 100.00 | 0.65 | 43.33 |
| NC 59 | 34.5 | 36 | 1.5 | 1.5 | 100.00 | 0.85 | 56.67 |
| NC 59 | 36 | 37.5 | 1.5 | 1.4 | 93.33 | 1.35 | 90.00 |
| NC 59 | 37.5 | 39 | 1.5 | 1.5 | 100.00 | 1.3 | 86.67 |
| NC 59 | 39 | 40.5 | 1.5 | 1.5 | 100.00 | 1.2 | 80.00 |
| NC 59 | 40.5 | 42 | 1.5 | 1.5 | 100.00 | 0.85 | 56.67 |
| NC 59 | 42 | 42.5 | 0.5 | 0.4 | 80.00 | 0.2 | 40.00 |