1101A
139
1101A-82
5 cm

Datum for Levels & Bearings. Glenorchy Sewerage Survey.
Survey by J. Deeth. April 1945.
Closing error of surround 1. in 1563.

F.B. 87. L.B. 86.

Public Works Department. Tasmania.

SOUTHERN REGIONAL WATER SUPPLY INVESTIGATION.
TRIAL STORAGE SITE NEAR GLENORCHY.

	Prepared.	Checked.		
Scale. {Plan 50 Feet / Locality Plan. 1. Mile} to an inch.				2997.S. 2.
Drawing.	A. A. Holmes. May. 1945	R.H. 2.5.45		
Tracing	A.A.H. May. 1945.			
Design.				
Supervision. A. A. Holmes Chief Draftsman.	R. A. Ritchie Hydraulic Engineer.		H. W. Knight CHIEF ENGINEER.	