

1775

80g

5 cm

PLATE: 2.




FIG. 1.




Fig. 2.



Three electrode Resistivity log
Drill hole at bottom of quarry.

Fig. 3.



Electrode Arrangement.

Geophysical Survey
for
Goliath Portland Cement Co.
Railton, Tasmania.
Resistivity Survey

MINES DRAWING OFFICE
FILE COPY
PLEASE RETURN

1775-37

G.359-12