



2373  
H3



OONAH

Post-Office  
Lode


Open cut  
Breaches  
Lode



LEGEND

- Geophysical traverse with station No surveyed by IP method
- IP Anomaly
- Swamp
- Shaft (inaccessible)
- Road

PLAN  
of  
IP ANOMALIES



2373/50

2373-50

(BASED ON K55/B7-71)