








AMBLESIDE SUBDIVISION DEVONPORT TEST PITS



- 2 Test pit position & No.
-  Seepages
-  Breaks in topography
-  Dolerite outcrop
-  Areas in which development is not recommended
- Contours in feet

Geologist: W.L. Matthews
Drawn: T.J. Walsh



3367 B

360

3367 B