

4072



ROCK CONDITIONS IN THE LAKE DOBSON AREA
 GEOLOGIST: P. C. STEVENSON JAN 1976

MT. MAWSON
 Map Scale: 1:2000
 Contour Interval: 2m
GUTTERIDGE, HASKINS & DAVEY PTY LTD
 CONSULTING ENGINEERS - PLANNERS - SURVEYORS
 BRISBANE - CAIRNS - CANBERRA - DARWIN - HOBART
 LAUNCESTON - MELBOURNE - PERTH - SYDNEY

SCALE	
DESIGNED	
DRAWN	
TRACED	
CHECKED	
APPROVED	
INITIAL	DATE

N° 4072
 DRAWING No. 12/16/01

5 cm