



5 cm



Potentially <sup>large</sup> Wedge Failures with Tension cracks visible on upper and side faces

5 cm



FACE WITH DIP DIRECTION AND DIP



ANGLE OF INTERSECTION OF TWO FACES AND DIRECTION OF SLIDING

S05

4218 A

\*

\*4218

(SYMBOLS) KEY