



LEGEND

- Slope direction and angle
- Change in slope, downslope indicated
- Change in slope, upslope indicated
- Ridge
- Small drainage valley
- Swampy ground
- Tree with downslope lean
- Seepage
- Basalt boulders
- Clay exposed
- Area of internal drainage
- Deformation in house or retaining wall
- Old adit
- Piling
- Toe area of active landslide
- Crack in retaining wall direction of separation indicated



LD 480 (Mines 4254A)

**BEAUTY POINT LANDSLIPS A & B**  
 UNDER LOCAL GOVERNMENT ACT (Nº2) 1973

4254A

