


5 cm

- Slope angle and direction.
- Break of slope-downslope side indicated.
- Break of slope-upslope side indicated.
- Headscarp of active landslide - vertical displacement indicated (m)
- Outline of old dormant landslide.
- Spring.
- Marshy ground
- Abandoned timber dwelling
- Test pit
- Development not recommended.
- Previous subdivision.



RANNOCH CRESCENT PROJECT
MORPHOLOGICAL MAP

R.C. DONALDSON - JULY 1980

0 50 m.

Figure 2