

4747

514

5 cm

Depth (m)

0  
2  
4



TP1



TP2

(m)


0  
2  
4

TP1 Test pit

⊥ Fence

---?--- Probable old landslide


— A — Line of section



Clay topsoil (CH).



Iron enriched clay (CH).




Extremely to highly weathered basaltic material.





Residual clay (CH).



Residual clay with pockets of extremely weathered basalt.



SECTION A B



LOCATION PLAN

0 400 m

0 50 m

T. MCCARTHY - LOT 20 BRADDONS LOOKOUT ROAD, LEITH  
GEOLOGICAL INVESTIGATIONS

R.C. DONALDSON DECEMBER 1980

FIGURE 1