

027

752028

DRILLHOLE P-05

Depth (m)

Lithologic Description

0.00 - 2.40

Soil: red-brown; silty, loamy; contains weathered basalt fragments.

2.40 - 3.50

Basalt: predominantly talus.

3.50 T.D.