

| Date. | Locality. | No. of Bore. | Footage. | Total Depth. | SHIFTS PER DAY. | | Strata. | Remarks. |
|--|---------------------------------|--------------|----------|--------------|----------------------------|---------|---------------------------------|----------|
| | | | | | Men. | Shifts. | | |
| AMG Co-ords: 582865 E 5471102 N | | | | | NO 9 D (Singe) Ref N° 1124 | | | |
| June 12 | Baseline | NO 9 D | 40 | 40 | 3 | 1 | Surface 0-1 | 1' |
| 13 | 1 ch. 56° 30' W from NO 8 D. | | 35 | 75 | | | Cement 1-6 | 5' |
| 14 | | | | | | | sand 6-16 | 10' |
| 17 | | | 22 | 97 | | | drift 16-56 | 40' |
| 18 | | | | | | | sediment 56-62 | 8' |
| | | | | | | | drift 64-69 | 5' |
| | | | | | | | sediment 69-84 | 15' |
| | | | | | | | drift 84-92 | 8' |
| | | | 43 | 140 | | | sediment 92-120 | 28' |
| July 3 | | | 7 | 147 | | | wash 120-141'6" | 21'6" |
| | | | | | | | soft shale bottom 141'6"-147 | 5'6" |
| Broken sludge pump - NO 9 D from 196640 to 2-7-48. | | | | | | | | |
| Av. 1.2 | | | | | | | | |

| AMG Co-ords: 582881 E 5471110 N. | | | | | | Ref N° 1125 | | | |
|----------------------------------|----------------|---------|----|-----|--|-------------|-----------------------------------|-----|--|
| June 19 | 1 ch 56° 30' W | NO 10 D | 29 | 29 | | | Surface 0-1 | 1' | |
| 20 | from NO 9 D. | | 40 | 69 | | | Cement 1'-11' | 10' | |
| 21 | | | 21 | 90 | | | drift 11'-39' | 28' | |
| 23 | | | 37 | 127 | | | sediment 39'-51' | 12' | |
| 24 | | | 23 | 150 | | | pur 51'-58' | 7' | |
| | | | | | | | drift (band of animal) 58'-73' | 15' | |
| | | | | | | | pur 73'-93' | 20' | |
| | | | | | | | drift 93'-132' | 39' | |
| | | | | | | | wash 132'-136' | 4' | |
| | | | | | | | drift 136'-142' | 6' | |
| | | | | | | | wash 142'-152' | 10' | |
| | | | | | | | hard shale bottom 152'-153' | 1' | |
| Av. 3.02. | | | | | | | | | |

| AMG Co-ords: 5828546 E 5471094 N. | | | | | | Ref N° 1126 | | | |
|-----------------------------------|-----------------|---------|----|-----|--|-------------|--------------------------------|-----|--|
| 25 | 1 ch. 56° 30' W | NO 11 D | 12 | 12 | | | Surface 0-1 | 1' | |
| 26 | from NO 10 D | | 40 | 52 | | | purgy drift 1-21' | 20' | |
| 27 | | | 41 | 93 | | | drift 21'-52' | 31' | |
| July 1 | | | 37 | 130 | | | pur 52-64' | 12' | |
| 2 | | | | | | | drift 64'-75' | 11' | |
| 25 | | | 5 | 135 | | | pur 75'-93' | 18' | |
| | | | | | | | drift 93'-113' | 20' | |
| | | | | | | | pur 113'-125' | 12' | |
| | | | | | | | drift with stones 126'-132' | 7' | |
| | | | | | | | hard shale bottom 132'-135' | 2' | |
| Trace | | | | | | | | | |

| AMG Co-ords: 582828 E 5471086 N. | | | | | | Ref N° 1127 | | | |
|----------------------------------|--------------|------|----|-----|--|-------------|--------------------------------|------|--|
| 4 | Liche | 12 D | 35 | 35 | | | Surface 0-1' | 1-0' | |
| 5 | 56° 30' W | | 40 | 75 | | | purgy drift 1-20' | 19' | |
| 8 | from NO 11 D | | 23 | 98 | | | drift 20-52' | 32' | |
| 9 | | | 24 | 124 | | | pur 52-60 | 8' | |
| | | | | | | | drift 60'-93' | 33' | |
| | | | | | | | wash 93'-95' | 2' | |
| | | | | | | | pur 95'-106' | 11' | |
| | | | | | | | drift 106'-116' | 10' | |
| | | | | | | | wash 116'-120' | 4' | |
| | | | | | | | hard shale bottom 120'-122' | 2' | |