

Hole No.	262 Co-Ordinates		Collar Elevation	Date
	Easting	Northing		
W43	535 800	5 329 100	229.16	11.6.81

Depth in Metres	Description
-----------------	-------------

0-4	Dolerite rubble
4-6	Mudstone (black), sandstone - weathered, dolerite - rubble
6-8	Mudstone (grey), traces of sandstone - grey and clayey
8-10	Sandstone - grey and medium grained, siltstone - grey, black
10-12	Sandstone - grey and medium grained, siltstone - grey black
12-14	Black carbonaceous material, sandstone, grey
14-20	Sandstone - grey
20-22	Sandy/silty - clay material, sandstone, grey.
24-30	Lost
30-34	Sandstone - grey with clayey texture
34-36	Sandy/clayey material, grey sandstone, minor amounts
36-40	Sandy/clay material, traces of sandstone
40-52	Mudstone grey
52-54	Mudstone grey, sandstone, grey and fine grained.
54-56	Dolerite, mudstone - grey
56-60	Dolerite
60-62	Dolerite (80%), Mudstone -(light grey colour)
62-66	Dolerite
66-68	Dolerite, minor siltstone and sandstone
68-72	Siltstone, dolerite, very minor amounts
72-74	Siltstone (grey/green) minor amounts, mudstone (70%), Dolerite (30%)
74-76	Dolerite (90%), minor siltstone from uphole contamination about 10%.
TOTAL DEPTH - 76m	