

Hole No.	Co-Ordinates		Collar Elevation	Date
	Easting	Northing		
W69	544 000	5 327 700	293.39	

Depth in Metres	Description
0-2	Broken dolerite and soil
2-6	Weathered dolerite
6-8	Dark grey dolerite continues throughout hole, becomes greenish in colour at 60m. Note: 84m in W66 is very similar
	NB: This hole was pumping 200 gallons/hour of water which caused its abandonment
8-115	Fresh dolerite with small grain size.
	TOTAL DEPTH 115m