

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7825

Locality: Smithton W. Timms Drill: Surge  
 Bore No.: 10 X Commenced: 7<sup>th</sup> January 1947. Completed: 13 January 1947.  
 Location of Bore: 26-1-47 7. Demonside  
 Co-ordinates of Collar: AM660-ords: 332600E 5481000 N. R.L. of Collar: \_\_\_\_\_  
 Bearing: \_\_\_\_\_ Inclination: \_\_\_\_\_ Final Depth: \_\_\_\_\_ Ref No. 1219

BORE LOG

Date	Footage	Total Depth	BORE LOG				Particulars of Core	Details of Ore Intersection
			From	To	Core	Thickness		
Jan 7	11	11	0'0"	1'0"		1'0"	Surface	
8	9	20	1'0"	5'6"		4'6"	Stones.	
9	6	26	5'6"	12'0"		6'6"	Pug.	
FF	2	28	12'0"	28'0"		14'0"	Hard sandstone.	
13	2	30	28'0"	30'0"		2'0"	Hardstone.	Water struck at 28 ft flow 200 gls Per hour.

11 201

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7825

Locality: *Montagu D.B. Williams Jnr.* Drill: *Surge*  
 Bore No.: *11* Commenced: *16 January 1947* Completed: *17 January 1947*  
 Location of Bore: .....  
 Co-ordinates of Collar: ..... R.L. of Collar: .....  
 Bearing: ..... Inclination: ..... Final Depth: .....

BORE LOG

Date	Footage	Total Depth	BORE LOG			Particulars of Core	Details of Ore Intersection
			From	To	Core Thickness		
<i>Jan 16</i>	<i>2</i>	<i>27'</i>	<i>25'0"</i>	<i>28'0"</i>	<i>3'0"</i>	<i>Blue Stone.</i>	
<i>17</i>	<i>1</i>	<i>28</i>				<i>This Bore was in well 25ft deep.</i>	

11 202

*See separate sheet.*