

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7825

10

Locality: Gladstone Drm: Cape
 Bore No.: 10 J Commenced: 1st May 1941 Completed: 5-5-41
 Location of Bore: 2 chains west of No 9 J
 Co-ordinates of Collar: PM66ords: 553721E 5469952N R.L. of Collar:
 Bearing: Inclusion: vertical Final Depth: 79' (71)

RJ N 5 1289

BORE LOG

Date	Footage	Total Depth	From	To	Core	Thickness	Particulars of Core	Details of Ore Intersection
May 1	20	20	0'	1	1	1	surface	
2	41	61	1	2	1	1	sand	
		79	2	10	8	8	clay	
			10	15	5	5	sand	Trace
			15	18	3	3	sediment	
			18	20	2	2	wash	
			20	48	28	28	dirt	
			48	50	2	2	clinker	
			50	59	9	9	dirt	
			59	71	12	12	sediment	
			71	79	8	8	slate bottom	

930

11 329