

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7825

38

Locality: Gladstone Dr. Calyx Ref. No. 1315
 Bore No.: 23 Commenced: Oct 7th 1941 Completed: Oct 9th 1941
 Location of Bore: 1 chain west of No 15
 Co-ordinates of Collar: AM6 Co-ords: 5835 E 5469691 N R.L. of Collar: _____
 Bearing: _____ Inclination: Vertical Final Depth: 115 (109)

Date	Footage	Total Depth	BORE LOG					Details of Ore Intersection
			From	To	Core	Thickness	Particulars of Core	
1941								
Oct. 7	43	43	0	1	1	1	surface	
8	50	93	1	3	2	2	sand	
9	22	115	3	10	7	7	clay	
			10	19	9	9	sediment	
			19	23	4	4	drift	
			23	30	7	7	pyg	
			30	34	4	4	drift	
			34	50	16	16	pyg	
			50	58	8	8	drift	
			58	60	2	2	sediment	
			60	63	3	3	drift	
			63	69	6	6	sediment	
			69	91	22	22	drift	
			91	102	11	11	wash	
			102	107	5	5	drift	
			107	109	2	2	wash	
			109	115	6	6	date bottom	

Trace.

10 019

986