

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7825

Locality: Gladstone Drm: Surge Ref No: 1357
 Bore No.: Nº 20 Commenced: 14th July 1941 Completed: 15-7-41
 Location of Bore: 1 chain east of Nº 10
 Co-ordinates of Collar: W. 6. 6. 6. 583776 E 5469351 N R.L. of Collar: _____
 Bearing: _____ Inclination: vertical Final Depth: 82. (81)

| Date | Footage | Total Depth | BORE LOG | | | | | Details of Ore Intersection |
|-----------|---------------|-------------|----------|----|------|---------------|-------------------------------|-----------------------------|
| | | | From | To | Core | Thickness | Particulars of Core | |
| July 1941 | | | | | | | | |
| July 1941 | 45 | 45 | 0 | 1 | 1 | 1 | surface | Trace |
| | 37 | 82 | 1 | 3 | 2 | 2 | cement | |
| | 38 | | 3 | 16 | 13 | 13 | puddy air | |
| | | | 16 | 22 | 6 | 6 | air | |
| | | | 22 | 31 | 9 | 9 | sediment | |
| | | | 31 | 62 | 31 | 31 | air | |
| | | | 62 | 66 | 4 | 4 | wash | |
| | | | 66 | 81 | 15 | 15 | same sediment probably bottom | |
| | | 81 | 82 | 1 | 1 | slate bottom. | | |

10 103

0 1/4