

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7825

108

Locality: Gladstone Drift: Surge  
 Bore No.: 11T Commenced: 7th December 1941 Completed: 14-11-41  
 Location of Bore: one chain east of No 10 T  
 Co-ordinates of Collar: AM6 words: 543685 E 5469425 N R.L. of Collar: \_\_\_\_\_  
 Bearing: \_\_\_\_\_ Inclination: vertical Final Depth: 129 (127)

Ref No: 13465

BORE LOG

Details of Ore Intersection

Date 1941	Footage	Total Depth	BORE LOG					Particulars of Core	Details of Ore Intersection
			From	To	Core	Thickness			
Nov 7	25	25	0	1	1	1	surface	90'8" - 102 1.51 oz. 70% conc p.c.y	
10	39	64	1	6	5	5	sediment	102 - 113'4" 1.36	
11	31	95	6	14	8	8	puddy airfr	113'4" - 124'8" 52.5	
12	10	105	14	28	14	14	pudd	124'8" - 127' 147.0	
13	18	123	28	32	4	4	airfr		
14	6	129	32	36	4	4	wash		
			36	78	42	42	airfr	Av. = 7.6 oz. 70% conc. p.c.y	
			78	95	17	17	pudd		
			95	97	2	2	wash		
			97	108	11	11	airfr		
			108	127	19	19	wash		
			127	129	2	2	hard slate bottom		

10 159

1210