

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7825

158

Locality: Gladstone Drm: Surge Ref No: 1435
 Bore No.: 33 X Commenced: 14 Aug 1942 Completed: 20th Oct. 1942
 Location of Bore: 2 chains west of 32 X
 Co-ordinates of Collar: AM6 cords: 5843 05 E 5407662 N R.L. of Collar: _____
 Bearing: _____ Inclination: vertical Final Depth: 120 (117')

| Date | Footage | Total Depth | BORE LOG | | | | | Details of Ore Intersection |
|--------|---------|-------------|----------|-----|------|-----------|---------------------|-----------------------------|
| | | | From | To | Core | Thickness | Particulars of Core | |
| 1942 | | | | | | | | |
| Aug 14 | 20 | 20 | 0 | 1 | 1 | 1 | surface | |
| 15 | 30 | 50 | 1 | 2 | 1 | 1 | sand | |
| 16 | 23 | 73 | 2 | 6 | 4 | 4 | cement | |
| Oct 19 | 10 | 83 | 6 | 22 | 16 | 16 | buggy drift | |
| 20 | 37 | 120 | 22 | 24 | 2 | 2 | peg | |
| | | | 24 | 82 | 58 | 58 | drift | |
| | | | 82 | 89 | 7 | 7 | peg | |
| | | | 89 | 100 | 11 | 11 | drift | |
| | | | 100 | 107 | 7 | 7 | peg | |
| | | | 107 | 112 | 5 | 5 | drift | |
| | | | 112 | 117 | 5 | 5 | drift wash stones | |
| | | | 117 | 120 | 3 | 3 | slat. | |

10 259

2220