

Ref No: 1463

Locality: Gledstone Drill: Surge
 Bore No.: 61 X Commenced: 16 April 1943 Completed: 20-4-43
 Location of Bore: 1/2 Chain west of N°55
 Co-ordinates of Collar: AMG Co-ords: 0584175 E 5467272 N. R.L. of Collar: _____
 Bearing: _____ Inclination: vertical Final Depth: 106 (104)

| Date | Footage | Total Depth | BORE LOG | | | | | | Details of Ore Intersection |
|-------------|---------|-------------|----------|-----|------|-----------|---------------------|--------|-----------------------------|
| | | | From | To | Core | Thickness | Particulars of Core | | |
| Apr 16 1943 | 25 | 25 | 0 | 1 | 1 | 1 | surface | Trace. | |
| Apr 19 | 50 | 75 | 1 | 2 | 1 | 1 | sand | | |
| Apr 20 | 31 | 106 | 2 | 10 | 8 | 8 | clay | | |
| | | | 10 | 39 | 29 | 29 | puggy drift | | |
| | | | 39 | 46 | 7 | 7 | pug | | |
| | | | 46 | 58 | 12 | 12 | puggy drift | | |
| | | | 57 | 65 | 7 | 7 | pug | | |
| | | | 65 | 80 | 15 | 15 | drift | | |
| | | | 80 | 85 | 5 | 5 | wash | | |
| | | | 85 | 98 | 13 | 13 | drift | | |
| | | | 98 | 101 | 3 | 3 | pug | | |
| | | | 101 | 104 | 3 | 3 | wash | | |
| | | | 104 | 106 | 2 | 2 | slate | | |

0283

10 314