






# BORING OR TEST PIT RECORD

SCHEME - LAKE ECHO P.D.	POSITION	CO-ORDINATES:	E:	N:	HOLE No. 245A 48
LOCATION - Menpeelya Canal		ON LINE:	BEARING:	AT CH:	
POSITION PLOTTED ON DRAWING No.:		FROM STN.:	BEARING:	DIST.:	
DATES: (a) BORED 6/11/54 (b) WATER TABLE:	LEVEL	SURFACE:	FORMATION:	WATER TABLE:	FILE No. 42/2
METHOD USED Auger DIAMETER: 6"		3028.2		3025.2	
SITE REMARKS: Grassy flat.	INCL.	HOLE BORED:	DEPRESSION ANG.:	INCL. BEARING:	SHEET OF SHEETS
		VERT/HOR/INC:			

STANDARD LEVEL	DEPTH	SAMPLE No.	GRAPHIC LOG	CLASSIFICATION	M. C. SAMPLE No.	M. C. IN SITU %	DRY DENSITY lbs. cu. ft.	REMARKS
	1'0"							Topsoil & Scree
				CL				Brown yellow grey medium plastic clay
	12'0"			CL				Brown yellow silty clay
	25'0"			CL				DO.
2999.2	29'0"							Hole stopped because of stone.  Reqd. 2994.0 Require 5.2' to this level.