

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7825

320

Locality: Gladstone Dr: Calyx
 Bore No.: 982 Commenced: 24th Sept. 1943 Completed: 27th 9-43
 Location of Bore: 49 north 40° east from N° 972
 Co-ordinates of Collar: AM 66 cords: 546305 E 5467398 N R.L. of Collar: (?)
 Bearing: Inclination: Vertical Final Depth: 87 (79)

Date 1943	Footage	Total Depth	BORE LOG					Particulars of Core	Details of Ore Intersection
			From	To	Core	Thickness			
Sept 24	40	40	0	1	1	1	surface		
27	47	87	1	6	5	5	clay		
			1	15	9	9	puddy drift		
			15	28	13	13	drift		
			28	35	7	7	sediment	Trace.	
			35	52	17	17	drift		
			52	54	2	2	py		
			54	73	19	19	drift		
			73	79	6	6	drift wash stones		
			79	87?	1	1	slate		

Ref No 1597

0023