

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7825

Ref No 17486

Locality: *Herrick*
 Bore No.: *3 B* Commenced: *29th September* Completed: *5th October*
 Location of Bore: *1/4 mile from 20*
 Co-ordinates of Collar: *General M66-ords: 575000 E 5449000 N* R.L. of Collar:
 Bearing: *Vertical* Inclination: *Vertical* Final Depth: *142' (138')*

BORE LOG

Date	Footage	Total Depth	BORE LOG					Particulars of Core	Details of Ore Intersection
			From	To	Core	Thickness			
<i>29</i>	<i>9</i>	<i>18'</i>	<i>0'</i>	<i>1'</i>	<i>1'</i>	<i>1'</i>	<i>Surface</i>		
<i>2</i>	<i>10</i>	<i>41'</i>	<i>1'</i>	<i>4'</i>	<i>3'</i>	<i>3'</i>	<i>Gravel</i>		
<i>3</i>	<i>10</i>	<i>50'</i>	<i>4'</i>	<i>15'</i>	<i>11'</i>	<i>11'</i>	<i>Log</i>		
<i>4</i>	<i>10</i>	<i>62'</i>	<i>15'</i>	<i>91'</i>	<i>76'</i>	<i>76'</i>	<i>Log & drift</i>		
<i>5</i>	<i>10</i>	<i>72'</i>	<i>91'</i>	<i>99'</i>	<i>8'</i>	<i>8'</i>	<i>Log with decomposed wood</i>		
		<i>82'</i>	<i>99'</i>	<i>119'</i>	<i>20'</i>	<i>20'</i>	<i>Log & drift</i>		
		<i>92'</i>	<i>119'</i>	<i>138'</i>	<i>19'</i>	<i>19'</i>	<i>Log</i>		
		<i>102'</i>	<i>138'</i>	<i>142'</i>	<i>4'</i>	<i>4'</i>	<i>Gravel</i>		
		<i>112'</i>						<i>Nil</i>	

0327