

DEPARTMENT OF MINES, TASMANIA—DRILLING RECORD.

7925

Locality: SCAMANDER
 Bore No. 1: Bore No. 2:
 Commenced: 10: 9: 59 18: 9: 59 Completed: 14: 9: 59 23: 9: 59
 Location of Bore: H.G. KEID'S PROPERTY - SCAMANDER See Air Photo ST HELENS, RUN 7, N° 25797
 Co-ordinates of Collar: AMG Co-ords: 605800E 5110400 N. R.L. of Collar:
 Bearing: Inclination: VERTICAL. Final Depth: Bore No. 1: 31 feet. Bore No. 2: 24' 6ins

Date	Footage	Total Depth	BORE LOG					Details of Ore Intersection
			From	To	Core	Thickness	Particulars of Core	
1959								
Sept. 10	19'	19'	0'	4'	-	4'	Sand. Ref Nos. 1836	Water struck at 20 feet. Flow 150 gallons per day. Quality Good.
" 11	9'	28'	4'	18'	-	14'	Sand and some slate.	
" 14	3'	31'	18'	26'	-	8'	Very hard sand.	
			26'	28'	-	2'	Some loose quartzite stones.	
			28'	31'	-	3'	Broken quartzite.	
	<u>BORE NUMBER 2.</u>							
Sept. 18	21'	21'	0'	14'	-	14'	Black Sand. Ref Nos. 1837	Water struck at 15 feet. Flow 200 gallons per day. Quality Good.
" 23	3' 6"	24' 6"	14'	16'	-	2'	Some clay and stones.	
			16'	20'	-	4'	loose stones and sand.	
			20'	21'	-	1'	loose quartzite and sand.	
			21'	24' 6"	-	3' 6"	Quartzite becoming harder.	

TNGO