

## Appendix A

### *Drilling logs from landscape groundwater investigations*

Table 1 Drilling log from the lowermost bore drilled on the Payne property

King Island Drilling - Salinity Investigation	
Geological log – Site: Payne Lower	
Depth (m)	Description of strata
0 – 1	Dark sandy clay soil
2 –10.8	Dark silty weathered granite, friable and oxidised
10.8 – 13.8	Grey weathered fractured granite
13.8 – 18.3	Fine grained granite – slightly weathered
Notes:	Lack of saprolite (decayed rock mass)

