

Table 3 Drilling log from the drilled off Haines Road on the Sutton property

King Island Drilling - Salinity Investigation	
Geological log – Site: Sutton 1 Southwest	
Depth (m)	Description of strata
0 – 14	Brown and grey fine sand
14 – 30	Very coarse grained granite – possibly pegmatite, very large feldspar crystals at 1 – 2 cm in width and slightly longer
Notes:	Lack of saprolite (decayed rock mass) Fractured rock aquifer

