

Table 4 Drilling log from the bore drilled within the Sutton property (internal farm)

King Island Drilling - Salinity Investigation	
Geological log – Site: Sutton 2 Southeast	
Depth (m)	Description of strata
0 – 2	Brown sandy soil
2 - 3	Brown/grey sandy soil
3 – 6	Grey sandy soil
6 – 7.8	Grey sand
12 – 13	Dark grey weathered limestone
15.3 – 17.1	Grey fossiliferous limestone
17.1 – 30	Dark blue/grey weathered metasedimentary rock
Notes:	<p>Lack of saprolite (decayed rock mass)</p> <p>Fracture set encountered at 25 metres with obvious signs of groundwater inflow</p> <p>Casing could not be installed below 19 metres because of sand collapse into the bore</p>

