

Table 6 Drilling log from the bore drilled on the Stellmaker property

King Island Drilling - Salinity Investigation	
Geological log – Site: Stellmaker	
Depth (m)	Description of strata
0 – 1,0	Organic rich sand with lignite like material
1 – 2	Dark gray silty clay
2.0 – 3.9	Dark organic rich sandy clay
3.9 - 7.0	Grey granite, not weathered (fresh)
7.0 - 8.9	Grey fractured with weathering along fractures
8.9 – 10	Sold granite (fresh)
Notes:	Complete lack of saprolite (decayed rock mass) Fractured rock aquifer

