

**Table 7 Drilling log from the bore drilled on the Bowling property**

<b>King Island Drilling - Salinity Investigation</b>	
<b>Geological log – Site: Bowling</b>	
<b>Depth (m)</b>	<b>Description of strata</b>
0 – 2	Red silty clay soil
2 - 3	Grey silty clay/weathered
3.3 – 5.8	Grey oxidised metasediment appearance of siltstone/mudstone
5.8 – 9.2	Grey hard metasediment (slate)
9.2 –18.3	Grey hard metasediment fractured along joint planes
Notes:	<p>Complete lack of saprolite (decayed rock mass)</p> <p>Site appears to be located over the immediate contact zone between the granites and the metamorphic rocks (as per Knowles site)</p> <p>Fractured rock aquifer</p>
No image	