

Table 8 Drilling log from the bore drilled on the Morris property (Bore 1)

King Island Drilling - Salinity Investigation	
Geological log – Site: Morris 1	
Depth (m)	Description of strata
0 – 3	Dark silty sand with mica
3 - 4	Grey weathered granite
4 - 8	Blue/grey granite, not weathered
8 - 10	Blue/grey granite, not weathered, broken along shear planes, Shear planes inclined at a steep angle Some mineralisation along shear planes Some narrow bands of weathering along shear planes (up to 10 mm)
Notes:	Lack of saprolite (decayed rock mass) Fractured rock aquifer
No image	