

Table 9 Drilling log from the bore drilled on the Morris property (Bore 2)

King Island Drilling - Salinity Investigation	
Geological log – Site: Morris 2	
Depth (m)	Description of strata
0 – 2.28	Dark organic rich silty clay soil
2.28 – 4	Dark silty clay with iron mottling
4 – 6.3	Grey fractured granite, some weathering along broken shear zones that appear in some places down the profile
6.3 – 12	Grey granite
Notes:	Lack of saprolite (decayed rock mass) Fractured rock aquifer
No image	