

Shuffled plant from Bonner plains
 2-9-55 commenced to work at Stanhope
 8-9-55 Bob Melorby 6 shifts self 3 1/2 shifts

(9)

Site 3 Stanhope Hole 9

Soil
 decomposed debris
 of sandstone.

5-9-55
 plowing plant
 in position
 8-9-55
 Drilled 12'
 Ran 5'

6-9-55 Reading pipes
 + 700 ft pipe
 7-9-55 Rebuilt 10' pump
 engine
 9-9-55 drilled 24'
 Ran 5' 6'

Sand Stone

Sandstone
 + Bands of
 clay
 transverse

Sandstone
 + grey sandstone
 or mudstone.

9" clay
 1' coal
 3' mudstone
 + clay
 2' 9" coal
 + mudstone.

2597

1/2 mudstone
 coal.

3 float