

UNITY MINING LTD

HENTY GOLD MINE TASMANIA SURFACE DRILL SITE CHECKLIST B. SITE EXIT SIGN OFF

Hole No.:	LSUD01/2 & 3	Drilling Contractor:	Edrill
Location:	Lakeside - Tullah	Drilling Supervisor:	Jamie Kaye
ML/EL:	EL34_2010	Supervising Geologist:	Mike Blake
Drill Rig:	UDR200	JSEA Required*:	Y Date: 1 / 3 / 12

Site Inspection Notes

	Yes	No	Comments/Initials
Drill Pad			
All waste material removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Ear plugs, gloves, rags	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hydrocarbon waste/matting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Drill rods/bed logs removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hole sighting pegs removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hole Collar			
Hole grouted	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Cement grout cleaned up	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hole capped/numbered	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hole collar stable/secured	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hole making water	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Sumps			
Matting/booms removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
All waste material removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Sump barricading removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Water Supply			
Supply pump removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuels/oils removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
All waste material removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Water line removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Sign Off			
Drilling Supervisor:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Signature: <input type="text"/> Date: 1 / 3 / 12
Driller:	<input type="checkbox"/>	<input type="checkbox"/>	Signature: <input type="text"/> Date: / /
Supervising Geologist:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Signature: <input type="text"/> Date: 1 / 3 / 12

**photos of 'signed-off' drill sites must be taken by supervising geologist*

Note:

*

JSEA must be completed before ALL drill rig moves (ie between drill sites)



June 2012

EL34_2010 - Lakeside/Tullah

Abandoned Drill Site DDH: LSUD01 to 3

Collar LSUD01: (MGA94) East: 384441.2

North: 5375616.6

RL: 166.0m

Total Depth: 515.4m

Collar LSUD02: (MGA94) East: 384442.6

North: 5375616.6

RL: 166.0m

Total Depth: 480.6m

Collar LSUD03: (MGA94) East: 384440.1

North: 5375616.6

RL: 166.0m

Total Depth: 482.4m



June 2012

EL34_2010 - Lakeside/Tullah

Abandoned Drill Site DDH: LSUD01 to 3

Collar LSUD01: (MGA94) East: 384441.2

North: 5375616.6

RL: 166.0m

Total Depth: 515.4m

Collar LSUD02: (MGA94) East: 384442.6

North: 5375616.6

RL: 166.0m

Total Depth: 480.6m

Collar LSUD03: (MGA94) East: 384440.1

North: 5375616.6

RL: 166.0m

Total Depth: 482.4m

